

TWO STROKE

SUZUKI

2-Stroke

Service Bulletin Index

GT

NO.	MODEL	SUBJECT
1	GT750	COOLING SYSTEM
2	GT750	OIL STARVATION
3	GT750	CRANKCASE AND GEAR REPLACEMENT
4	GT750	STARTER CLUTCH MODIFICATION
5	GT750	NEW STYLE CYLINDER HEAD BOLT WASHER
6	GT750	CRANK SHAFT MODIFICATIONS
7	GT750	INCREASED PERFORMANCE
8	GT550J	PRIMARY GEAR NOISE
9	GT380	KICK STARTER DRIVE GEAR AND OIL PUMP DRIVEN GEAR MODIFICATION
10	GT380	INCREASED TRANSMISSION OIL CAPACITY
11	GT250	DRIVE SHAFT/TOP GEAR
12	GT185	DISC BRAKE MANUAL ADDENDUM
13	GT550/750	EXHAUST COUPLER SEALANT
14	GT380/550/750	BATTERY BREATHER LOCATION
15	GT380/550/750	AIR CLEANER SERVICING
16	GT380/550/750	OPTIONAL SPROCKETS AND CHAIN
17	GT330/550/750	CONTACT BREAKER CAMS
18	GT330/550/750K	SRIS OIL STRAINER
19	GT250/380/550/ 750	DISC BRAKE MODIFICATION
20	GT250/380/550	NEW STYLE SPARK PLUG CAP BOOT
21	GT380/550/750L	FUEL STARVATION AT HIGH RPM
22	GT380/550/750	INSTRUCTIONS FOR USING CARBURETOR SYNCHRONIZATION TOOL
23	GT380/550	WIRING HARNESS TEMPORARY COLOR CODE CHANGES
24	GT250	BURNED OUT HEADLIGHT BULB
25	GT750	CYLINDER PULLER TOOL SET
26	GT550	STARTER CLUTCH CHANGE
27	GT185/250/380 550	SPARK PLUG CAPS

GT

NO.	MODEL	SUBJECT
28	GT500	PEI INSPECTION
29	GT550/750	2ND DRIVE AND DRIVEN GEARS
30	GT250A	IGNITION TIMING MARKS
31	ALL GT'S	CONSTANT ON HEADLIGHT
32	GT250	CHANGES FROM 1975 TO 1976
33	GT550	IMPROVED REAR BRAKE PERFORMANCE
34	GT500	SHIFT CAM GUIDE BOLT LOCATION
35	GT250	CYLINDER HEAD, SPARK PLUG, AND CARBURETION CHANGES
36	GT750	SURGING
37	GT380/550/750	FUEL COCK SEEPAGE
38	GT380/550/750	GEAR SHIFTING SWITCH
39	GT 500 A, B	FRONT FENDER MOUNTING METHOD
40		
41		
42		
43		
44		
45		
46		
47		
48		
49		
50		
51		
52		
53		
54		

SUZUKI SERVICE BULLETIN

Bulletin No. GT-1

Date May 1, 1975

SUBJECT: GT750 COOLING SYSTEM

Read & Initial

Manager _____

Parts _____

Service _____


Due to the specialized knowledge required to correctly service the liquid cooling system on the new GT750, the following information has been compiled as a ready reference.

Coolant: "Suzuki CCI Antifreeze and Summer Coolant" is recommended exclusively by the factory for use in the GT750. Tests have shown that no other brand of coolant manufactured in the United States meets the specialized requirements of this motorcycle cooling system.

Suzuki CCI Coolant.....Part No. 99000-24120 is available in 2 liter cans (2.1 U. S. quarts).*

Set-Up: Each machine is serviced with a 50/50 mixture of distilled water and Suzuki CCI Coolant at the factory. This protects the cooling system to a temperature of -24° Fahrenheit. (-31°C). This mixture will probably last for two years or 20,000 miles under normal use. Do not exceed a cooling mixture ratio of 60% Antifreeze as its anti-freezing effectiveness does not increase beyond this ratio. Conversely, do not go below a cooling mixture ratio of 30% Antifreeze in summer weather. This amount is required at all times for anti-corrosion and cooling. Use distilled water only for mixing.

Cooling System Capacity: The specified cooling system capacity is 4.5 liters or 4.75 U. S. quarts. The cooling mixture should be maintained 5-15mm from the bottom of the radiator reservoir tank. To facilitate daily inspection of this level, a white level plate is located inside the radiator refill pipe. The cooling solution should be maintained near this plate at all times. A daily inspection should be made of the cooling mixture level before starting the engine.



Cooling solution level

Maintenance: Although the cooling solution capacity is 4.5 liters, approximately 500 cc will remain trapped after draining or flushing; unless the engine is disassembled. Therefore, after normal draining or flushing, the refill capacity will be 4 liters (4.22 U. S. quarts).

To flush the cooling system, remove all engine water plugs and let drain. With the engine cold, flush with a water hose through the radiator opening. Replace the water plugs and run the engine for ten minutes with a flushing agent. Drain and flush again with water. Refill with the proper cooling mixture.

When refilling the system it will be necessary to run the engine until the thermostat opens, before the system can be filled to capacity. Running the engine at idle for ten minutes should accomplish this.

A container with a pre-mixed solution of the correct distilled water/anti-freeze ratio should be kept on hand to replenish whatever normal cooling mixture loss occurs during use. Refilling with water only will result in diluting the cooling mixture after a while.

The radiator cap pressure is rated at 13 p.s.i. J and K models: A cooling fan is installed behind the radiator and is controlled by a thermostat switch set to activate at a water temperature of 220°F. The fan will then operate until the cooling mixture temperature drops to 212°F. If for some reason you wish to activate the fan to run before a temperature of 220° F is reached, disconnect the brown wire from the thermo-switch and the fan will operate.

Anti-leak Chemicals: At the factory 14 grams (½ oz.) of "Bars-Leaks" brand anti-leak chemical is installed in the cooling system of each GT750. NO ADDITIONAL ANTI-LEAK should be added, except after completely flushing the system and replenishing with new cooling solution. The inner diameter of the radiator tubing is only 1.5mm. Consequently radiator blockage can become critical. "Bars-leak" is capable of plugging a hole 1mm in diameter.

This fact, plus any incidental corrosion which might occur if a proper cooling mixture is not maintained, could result in clogging of the radiator leading to engine failure. Use of any other brand anti-leak is not recommended.

Storage: It is not advisable to drain the cooling system when the motorcycle is to be stored, since this would initiate corrosion in the aluminum radiator, cylinder and cylinder head.

(cont.)

WATER PUMP IMPELLER CIRCLIP:

We have had several reports of water pump damage on the GT-750. This has been due to the impeller circlip, coming off the water pump shaft.

Therefor, whenever the water pump is disassembled, a new impeller circlip, Suzuki Part No. 08331-11109, should always be installed upon reassembly.

SUZUKI SERVICE BULLETIN


Bulletin No. GT-2
Date May 1, 1975

SUBJECT: GT750 OIL STARVATION

Head & Initial
Manager _____
Parts _____
Service _____

PROBLEM:

If care is not taken it is possible to pinch the inlet line from the oil tank to the oil pump when installing the oil pump cover. Pinching this line closed will result in no oil getting to the oil pump, or to the engine. Naturally this can cause a multitude of problems due to lack of lubrication.



CORRECTION:

1. Take special care that the oil pump inlet hose is routed around the crankcase air breather boss before installing the oil pump cover.
2. Before tightening down the screws holding the cover, check that the cover seats flush against the crankcase, without any gaps. If there is a gap, this would indicate that the hose might be pinched between the breather boss and the cover.
3. After tightening the screws, start the engine and check at the lines for any evidence of oil starving.

SUZUKI SERVICE BULLETIN

GT-3

Bulletin No. _____

Date May 1, 1975

SUBJECT: GT750 CRANKCASE AND GEAR REPLACEMENT

(Revised December 19, 1975)

REFERENCE: Service Bulletin #GT-29

Read & Initial

Manager _____

Parts _____

Service _____

The crankcase, 1st driven, 2nd driven and kick starter drive gears of the GT750 will be selection-assembled to obtain the optimum backlash of the gears for less noise from the transmission. Install the most suitable gears according to the following instructions when replacing these parts.

A. Installation of parts

1. When replacing the CRANKCASE ASSEMBLY:

- a. The crankcase assembly is supplied with the 1st driven, 2nd driven and kick starter drive gears with which the optimum backlash is obtained. Therefore, install these gears when replacing the crankcase assembly.
- *b. Second drive gear is not supplied with the crankcase assembly, but for engines prior to number GT750-73059 it must be replaced in conjunction with second driven gear which is supplied with the crankcase assembly.

2. When replacing 1ST DRIVEN GEAR AND/OR 2ND DRIVEN GEAR:

- a. In this package of spare parts, there are two gears classified by size, one is painted yellow and the other is painted white. When replacing this gear with a new one, check the paint color indicated on the crankcase originally fitted to the machine, then choose the most suitable gear in accordance with the chart on Page 2.

EXAMPLE: Fit the white painted gear if the crankcase is painted blue, green, or white.

- b. For engine numbers prior to GT750-73059 second drive gear must be replaced at the same time second driven gear is installed.

*Revised: December 19, 1975

U. S. SUZUKI motor corporation

13767 Freeway Drive • Santa Fe Springs, California 90570 • Phone: (213) 921-4461





(cont.)



3. When replacing the KICK STARTER DRIVE GEAR:

- a. Again there are two gears in the package, one is painted brown and the other is painted yellow. Choose the most suitable gear shown on the chart according to the paint color indicated on the crankcase.

EXAMPLE: Fit the brown painted gear if the crankcase is painted brown, black, red or yellow.

CRANKCASE COLOUR	1ST DRIVEN GEAR	2ND DRIVEN GEAR	KICK START DRIVE GEAR
B R O W N	YELLOW	YELLOW	BROWN
B L A C K			
R E D			
Y E L L O W			
B L U E	WHITE	WHITE	YELLOW
G R E E N			
W H I T E			
			

B. Change of part numbers

The part numbers of the relative parts have been changed as follows on page 3:

PART NAME	OLD PART NO.	NEW PART NO.	REMARKS
*Crankcase Ass'y.	11300-31851	11300-31852	includes crankcase ass'y., 1st driven, 2nd driven & kick scarter drive gears. For engines up to number GT750-73059. Second drive gear must also be installed. However, it is not supplied with crankcase assembly, and must be ordered separately.
Gear Comp, 1st Driven	24310-31000	24310-31821	includes two gears classified by size.
*Gear Comp, 2nd Driven	24321-31822	24300-37810	includes two gears classified by size. For engines up to number GT750-73059 second drive gear must also be installed at the same time.
Gear Comp, Kick Starter Drive	26240-31000	26240-31823	includes two gears classified by size.
*Second Drive Gear	24221-31000	24221-37000	Up to engine #GT750-73059 install second driven gear at the same time.

NOTE: For further details refer to Service Bulletin Number GT-29 of November 21, 1975.

*Revised: December 19, 1975

U. S. SUZUKI

SUZUKI SERVICE BULLETIN

Bulletin No. GT-3Date May 1, 1975SUBJECT: GT750 CRANKCASE AND GEAR REPLACEMENT

(Revised) 12-1985

Read & Initial

Manager _____

Parts _____

Service _____

The crankcase, 1st driven, 2nd driven and kick starter drive gears of the GT750 will be selection-assembled to obtain the optimum backlash of the gears for less noise from the transmission. Install the most suitable gears according to the following instructions when replacing these parts.

A. Installation of parts

1. When replacing the CRANKCASE ASSEMBLY:

The crankcase assembly is supplied with the 1st driven, 2nd driven and kick starter drive gears with which the optimum backlash is obtained. Therefore, install these gears when replacing the crankcase assembly.

2. When replacing 1ST DRIVEN GEAR AND/OR 2ND DRIVEN GEAR:

In this package of spare parts, there are two gears classified by size, one is painted yellow and the other is painted white. When replacing this gear with a new one, check the paint color indicated on the crankcase originally fitted to the machine, then choose the most suitable gear in accordance with the chart on Page 2.

EXAMPLE: Fit the white painted gear if the crankcase is painted blue, green or white.

3. When replacing the KICK STARTER DRIVE GEAR:

Again there are two gears in the package, one is painted brown and the other is painted yellow. Choose the most suitable gear shown on the chart according to the paint colour indicated on the crankcase.





EXAMPLE: Fit the brown painted gear if the crankcase is painted brown, black, red or yellow.

(cont.)

U. S. SUZUKI motor corporation

13757 Economy Drive • Santa Fe Springs, California 90670 • Phone: (714) 921-4441



CRANKCASE COLOUR	1ST DRIVEN GEAR	2ND DRIVEN GEAR	KICK START DRIVE GEAR
BROWN	YELLOW	YELLOW	BROWN
BLACK			
RED			
YELLOW			
BLUE	WHITE	WHITE	YELLOW
GREEN			
WHITE			
			

B. Change of part numbers

The part numbers of the relative parts have been changed as follows:

OLD		NEW		
Part Name	Part No.	Part Name	Part No.	Remarks
Crankcase Assy	11302-31802	Crankcase Assy	11304-31850	includes the 1st driven, 2nd driven & kick starter drive gears
Gear Comp, 1st Driven	24310-31000	Gear Set, 1st Driven	24310-31821	includes two gears classified by size
Gear Comp, 2nd Driven	24320-31000	Gear Set, 2nd Driven	24320-31822	includes two gears classified by size
Gear Comp, Kick Starter Drive	26240-31000	Gear Set, Kick Starter Drive	26240-31823	includes two gears classified by size

UPDATED

5. INTERCHANGEABILITY

The parts, except the crankshaft oil seal, may be interchanged. However, it is still highly recommended to use only the modified parts in order to thoroughly avoid a possible problem.

PART NUMBER:


DESCRIPTION	OLD NO.	NEW NO.
Starter Clutch Assembly	12603-31832	*12600-31832
Starter Clutch Gear	12620-31003	*12620-31004
Starter Clutch Gear Bearing	09263-25011	09263-25011
Crankshaft LH Oil Seal	09289-30001	*09263-30001

APPLICABILITY:

DESCRIPTION	PRODUCTION MONTH	ENGINE NO.
Starter Clutch housing	From April, 1972	From #27667
Starter Clutch Gear Bearing	From April, 1972	From #26030
Starter Clutch Gear	1. April and May production	1. #26030- #29045
Crankshaft LH Oil Seal	2. After old stock is exhausted	2. --

Note:

On future parts orders only the new type starter clutch parts will be supplied. However, the old type LH crankshaft oil seal will still be supplied until such time as the existing stock is exhausted. Therefore, when the old oil seal is retained in the unit and the starter clutch is modified or replaced, it is necessary to check the rib height of the oil seal and modify the same as shown.



*Update: March 5, 1976

U.S. SUZUKI *Motor Corporation*

1 FREEWAY DRIVE, SANTA FE SPRINGS, CALIFORNIA 90670



CABLE ADDRESS "COLLEDA"
TELEX: 657-419 SUZUKI CO. SFES
P.O. BOX 2107 TEL. (213) 921-4461

March 12, 1976

TO: All Suzuki Dealers
ATTENTION: Service Department Managers
SUBJECT: SERVICE BULLETIN #GT-4, PAGE 3 UPDATE

Attached is an updated page 3 of Service Bulletin #GT-4. Page 3 has been updated due to part number changes relating to the GT750 Starter Clutch. Please remove the original page 3 from your Service Bulletin binder and insert the updated page in its place.

U. S. SUZUKI
TECHNICAL SERVICE DEPARTMENT

SUZUKI SERVICE BULLETIN

Bulletin No. GT-5

Date May 1, 1975

SUBJECT: NEW STYLE GT750 CYL. HEAD BOLT WASHER

Read & Initial

Manager _____

Service _____

NOTICE

A new style washer has been designed for the cylinder head bolt of the GT750. The new style washer has a rubber seal molded around its inside surface as shown below.



OLD STYLE WASHER
(08322-11143)



RUBBER
SEAL

NEW STYLE WASHER
(09168-14008)

The rubber seal will prevent any possibility of coolant leaking past the washer and also prevent water from outside (rain or washing) passing in past the washer and rusting the bolt.

APPLICABILITY

GT750's on and after Engine Number GT750-51322 and Frame Number GT750-45213 have had the new style washers installed.

RECOMMENDATION

For units prior to the above Engine and Frame Numbers, it is recommended that the old style washers be replaced with new style washers whenever the cylinder head is removed from the GT750.

PARTS

The new style washer is now available from the U. S. Suzuki Parts Department, and the Part Number is: 09168-14008.

U. S. SUZUKI
TECHNICAL SERVICE DEPARTMENT



SUZUKI SERVICE BULLETIN

Bulletin No. GT-6

Date May 1, 1975

SUBJECT: GT750 CRANKSHAFT MODIFICATIONS

Read & Initial

Manager _____

Parts _____



Service _____

NOTICE:

The GT750 crankshaft assembly, has been modified in several ways to further increase its durability.

DETAILS OF MODIFICATIONS:

Side movement of the connecting rod is restricted on the small end, and the big end has been changed to a floating type as shown in the illustration below.



(cont.)




This has been accomplished by the following individual modifications.

1) Connecting rod:

The big end width has been reduced and a slot and a hole have been provided on the small end for better lubrication.



EARLY TYPE




MODIFIED

2) Crankshaft components:


A) Crank Wheels:

The width of the crank wheels has been reduced from 28.5mm to 27.5mm.




B) Pistons:

The pistons inside surface has been changed from a casting surface to that of a machined surface. The inside dimension between the wrist pin bosses has also been changed.



EARLY TYPE




MODIFIED

(cont.)



- C.) Thrust washer, connecting rod small end:
This thrust washer has been provided for the non-floating small end of the connecting rod. Two of these are used for each piston.




- D.) Thrust washer, crank pin bearing:
In order to have the connecting rod floating on the crank pin, this thrust washer has been modified as shown below.



- E.) Stud bolts:
Two of the twelve stud bolts on the crankcase assembly have been replaced with a new type shouldered bolt.



- F.) Cylinder gasket:
Two holes in the gasket have been enlarged from 11mm to 12.5mm in diameter to match the new type stud bolts.



● : ENLARGED

(cont.)

PART NUMBERS AND AVAILABILITY:

For assembly convenience, the new style crankshaft assembly consists of the following parts.

1. Pistons (3)
2. Thrust washers, connecting rod small end. (6)
3. Stud bolts. (2)
4. Crankshaft assembly.

The above crankshaft set does not include the cylinder base gasket, although it has been modified as explained in paragraph #2 (F). Consequently, when using the old style gasket, the necessary two holes should be enlarged before assembly.

PART NAME	OLD PART NO.	NEW PART NO.	AVAILABILITY
CRANKSHAFT SET	12003-31803	12200-31835	NEW ONLY
(CONNECTING ROD)	12161-31000	12161-31001	OLD & NEW
(CRANKSHAFT, R)	12221-31000	12221-31001	NEW ONLY
(CRANKSHAFT, MIDDLE)	12231-31000	12231-31001	NEW ONLY
(CRANKSHAFT, L)	12241-31002	12241-31003	NEW ONLY
(CRANK WEB, L)	12242-31000	12242-31001	NEW ONLY
(THRUST WASHER, CRANK PIN BEARING)	09160-24012	09160-24014	OLD & NEW
PISTON, R	12110-31000	12110-31001	OLD & NEW
PISTON, L	12120-31000	12120-31001	OLD & NEW
THRUST WASHER, CON-ROD SMALL END	NOT EXIST	09169-18001	AVAILABLE
STUD BOLT, CYLINDER	09108-10006	09108-10012	OLD & NEW
CYLINDER GASKET	11241-31000	SAME AS OLD	NEW ONLY

(cont.)

*The parts shown in parentheses are the modified components of the crankshaft.

PARTS STOCK:

Since the old style piston cannot be used on the new style crankshaft assembly, some of which are already in the field, it is recommended that you add the new style pistons to your parts inventory as soon as possible.


APPLICABILITY:

The crankshaft modification has been applied, on and from Engine Number 38060.

ASSEMBLING PROCEDURE:

If the new style crankshaft is to be used on the early type engine, the following procedure should be noted.

- 1) The pistons and thrust washers should be assembled as shown below.



NOTE: Two different pistons are used in the GT750 engine, and they are marked "R" and "L" on top of the piston crown. The "R" piston is for the right cylinder and the "L" pistons are for the left and middle cylinders.



TWO STROKE

SUZUKI

2-Stroke

Service Bulletin Index

T

NO.	MODEL	SUBJECT
1	T500	TRANSMISSION REPAIR
2	T250/305/350	DRIVE SHAFT/TOP GEAR
3	T500	INCREASED TRANSMISSION OIL CAPACITY
4	T500	SWING ARM PIVOT SHAFT
5	T/GT500	SHIFT CAM GUIDE BOLT LOCATION
6		
7		
8		
9		
10		
11		
12		
13		
14		
15		
16		
17		
18		
19		
20		
21		
22		
23		
24		
25		
26		
27		

SUZUKI SERVICE BULLETIN


Bulletin No. T-1
Date May 1, 1975

SUBJECT: T500 TRANSMISSION REPAIR

Read & Initial
Manager _____
Parts _____
Service _____

We would like to caution our service mechanics of the following problem areas when reassembling T500 transmissions:

- A. Do not interchange low gear slider wheel with 3rd gear slider wheel. If the transmission is assembled this way, the bike will jump out of first gear under any load. The difference between the two wheels is shown below:



- B. Do not switch the small needle bearing bushings on the ends of the transmission shafts. One is marked with a "D", this should be installed on the driveshaft (shaft with sprocket). The height of the two bushing pins in the case should not be more than 1.5mm (.060"). File off any excess height.

(cont.)


U. S. SUZUKI motor corporation

3767 Freeway Drive • Santa Fe Springs, California 90670 • Phone: (213) 921-4461



T500 Transmission Repair

- C. Be absolutely sure that all bushings and bearings are properly located over the pins in the lower crankcase. We have had ruined crankcases from failure to follow this simple step. This is not a factory defect and we expect the servicing dealer to bear the expense of repair for this type of damage.
- D. Use new snap rings when assembling gear locating rings to transmission shaft.
- E. Locate the gap in the snap ring away from the notches in the gear. This keeps the snap ring from popping loose if the tabs move over. Be sure that the ends of the snap rings do not butt. If they do, cut off until there is at least a 1/16" gap.



RIGHT
RING GAP CENTERED
BETWEEN GEAR NOTCHES

GAP IN RING
NOTCH
IN GEAR



WRONG
GEAR LOCATING RING
TABS CAN POP OUT

- F. In event of transmission problems, inspect:
 - 1. Pin in shift forks which rides in shift cam for galling. Remember that a little wear is inevitable.
 - 2. Shift cam grooves.
 - 3. Shift cam ratchet stop plate in right case for damage from hard shifting.
 - 4. Shift ratchet pins and springs for wear or weak tension.
 - 5. Engagement of dogs and slots for wear or "rounding - off."
 - 6. Bent shift fork rod.

SUZUKI SERVICE BULLETIN

Bulletin No. **T-2**

Date **May 1, 1973**

SUBJECT: T250, T305, T350 DRIVE SHAFT/TOP GEAR

Read & Initial


Manager _____

Parts _____

Service _____

NOTICE:

Top gear, driven, on the subject models has been increased in thickness and strength.



INTERCHANGEABILITY:

When using the new style driveshaft #24131-18002 with old style crankcases, the thrust washer #08211-22341 must be eliminated.

In the event that new cases are fitted and the old driveshaft re-used, washer #08211-22341 must be retained.

PARTS:

PART DESCRIPTION	OLD PART NO.	NEW PART NO.	QTY
ive shaft	24131-18001	24131-18002	1
Thrust washer	08211-22341		1

U. S. Suzuki
Technical Service Department



SUZUKI SERVICE BULLETIN

Bulletin No. T-3
Date May 1, 1975

SUBJECT: T500 INCREASED TRANSMISSION OIL CAPACITY

Read & Initial

Manager _____


Part _____

Service _____

To effectively increase the durability of the T500 4th and 5th gears, the transmission oil capacity has been increased from 1200cc to 1400cc. The increased oil capacity has been applied to the T500 since the beginning of the 1974 "L" model production.

A rubber flashboard applied to the primary oil transfer chamber in the lower crankcase half is used to accommodate the increased oil capacity. The flashboard keeps the additional oil from entering the primary case, and therefore protects the clutch from excessive drag.

The flashboard in position is illustrated below.



The T500's manufactured after December 1973 production will have the primary oil transfer partition cast 10mm higher instead of using the rubber flashboard.

The rubber flashboard is now available from the U. S. Suzuki Parts Department for T500's prior to the 1974 "L" model. Its application is strongly recommended whenever the crankcases are disassembled.



SUZUKI SERVICE BULLETIN


Bulletin No. T-4
Date Oct. 24, 1979

SUBJECT: T500 SWING ARM PIVOT SHAFT
REFERENCE: Service Bulletin #TC/TS-17

Read & initial
Manager _____
Parts _____
Service _____


NOTICE:

The shoulder radius of the T500 swing arm pivot shaft has been increased from 0.5mm to 1.0mm.



To accept the new type pivot shaft, the frame boss chamfer has also been increased 0.5mm.

NOTE: Should it be necessary to install a new type pivot shaft through an old type frame boss, simply move the washer from the nut side to the head side of the swing arm pivot shaft. The washer will conform to the shoulder radius of the pivot shaft.



PARTS:

The new type pivot shaft is now available from U. S. Suzuki's Parts Department. The part number is listed below:

DESCRIPTION

PART NUMBER

T500 swing arm pivot shaft

61411-13006

APPLICATION:

The new type swing arm pivot shaft has been installed on and from the following Frame Number:

3760-8-046

U. S. SUZUKI
TECHNICAL SERVICE DEPARTMENT

U. S. SUZUKI motor corporation
13757 Freeway Drive • Santa Fe Springs, California 90670 • Phone: (213) 921-4461



SUZUKI SERVICE BULLETIN

Bulletin No. T-5Date Mar. 19, 1976

SUBJECT: T500 SHIFTING CAM GUIDE BOLT LOCATION


UPDATED**REVISED**

Read & Initial

NOTICE:

We have received occasional reports of T500 transmission failure immediately after an engine or transmission overhaul. Upon disassembling and inspecting the transmission, two situations have been found. The first reason a transmission would fail was that an oil drain plug bolt from another model Suzuki (Example TS185/250) had been interchanged with the shift cam guide bolt during the overhaul. The second reason for the transmission failure was due to a magnetic oil drain plug that had been substituted instead of the shift cam guide bolt.

Note: Remove both bolts to drain transmission oil.



In both situations the bolt did not extend into the locating groove of the shift cam drum far enough to restrict the shift drum from sliding from side to side in the crankcases. When this happens the shifting forks slide with the shift cam, allowing two sets of gears to become engaged at the time. This results in severe damage to the gears, and requires their replacement.

Therefore, whenever a T500 is overhauled, or the transmission oil changed by your service department, the final inspection after reassembly should be the proper placement of the shift cam guide bolt.

U. S. SUZUKI

TECHNICAL SERVICE DEPARTMENT

U. S. SUZUKI Motor Corporation

13767 Fraewey Drive • Santa Fe Springs, California 90670 • Phone: (213) 921-4481



***REVISED: July 16, 1976